South Venice Waterways
Pre-Restoration Biological Assessment Monitoring Report


South Venice Waterways

Pre-Restoration Biological Assessment Monitoring Report

Prepared for:

Sarasota County

1001 Sarasota Center Boulevard

Sarasota, FL 34240

Prepared by:

HSW Engineering, Inc.

2810 Northdale Boulevard, Suite 210B

Tampa, FL 333624

(813) 968-7722

March 4, 2014
(Revised)

Main Body of Report »

Table of Contents

Introduction
- Background
- Purpose and Organization of Report

Methods
- Monitoring Locations
- Field Procedures

Site Descriptions
- Briarwood Ditch
- Siesta Ditch
- Woodmere Creek North
- Woodmere Creek South

Hydrometeorological Conditions Summary

Figures

Figure 1. Pre-restoration biological assessment monitoring locations

Tables

Table 1. Pre-restoration biological assessment monitoring locations in Venice, Florida

Appendices:

A – Aerial maps »

B – Compendiums of original and transcribed field sheet sets »

C – Photographs »

D – Data tabulations »